



Three Gasoline Tanks Repaired & Protected with CeramAlloy & CHEMCLAD

Client: Petrochemical Plant

Location: The Philippines

Problem: 40+ year old gasoline tank suffering from severe corrosion.

Solution: Grit blast interior surfaces; protect welded seams with CeramAlloy CP+AC; apply 2 coats of CHEMCLAD SC over all interior surfaces.

Cost: \$80,000 product and labor

Notes: This is one of three tanks that were protected with this ENECON system.



Approx. 8,000 sq. ft.
repaired & protected



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com